



66 Glen Avenue
Glen Rock, NJ 07452
Telephone: 201-301-1045
Fax: 201-857-8002
Email: info@johnsonsoils.com

September 8, 2023

HARBOR CONSULTANTS, INC
320 North Avenue East
Cranford, NJ 07016

Re: 113 North Avenue West
Cranford, NJ
JSC Job #23-582

To whom it may concern:

The following test pit was inspected on September 7, 2023 at the proposed seepage pit location. The test pit was dug with an excavator.

The test pit log is as follows:

TP-1

0" – 2½"	Asphalt
2½" – 6"	D.G.A
6" – 2'6"	Misc. fill – Sand, Asphalt, Gravel & Silt.
2'6" – 3'8"	Brown fine Sand and Silt.
3'8" – 8'	Redbrown fine Sand, some Silt, little Gravel.

No Ground Water'
No Seasonal High Water
No Mottling
The percolation rate at a depth of 6' is 0.6 in/hr.

If you have any questions please call.

Very truly yours,

Lisa V. Mahle-Greco, PE
Engineering Manager
NJ Lic. # 43197

MA, JG